Ironwood Forest National Monument Travel Management Plan and Environmental Assessment

(DOI-BLM-AZ-G020-2013-0033-EA)



ROUTES ON SENSITIVE SOILS and PM10 AIR QUALITY MANAGEMENT AREAS (EPA)
Surfacing with aggregate will be provided to reduce fugitive dust from unpaved roads, and alleviate damage from use of the roads under muddy conditions. Priority will be given to routes in the Non-Attainment Areas that receive the greatest amount of use.

- EPA_WEST_PINAL_PM10_NAA-N83
- RILLITO_PM10-NONATTAINMENT-AREA
- Sensitive Soil Types on Monument Lands

Map 10.1: Air Quality Management Areas and Sensitive Soils in the Monument.

This map shows the existing PM10 Non-Attainment Air Quality Management Areas in the vicinity of the Monument, which are potentially affected by fugitive dust emissions from sources in the Monument.

The map also shows the travel route designations for the Monument transportation system, established concurrently with the Resource Management Plan (Record of Decision approved February 2013) to accommodate access and achieve the purposes of the Monument.

- Road (Passenger car access, two lane)
- Primitive Road, (Type A- Medium truck access single lane 14 ft. width)
- Primitive Road, (Type B- 4WD light truck access single Lane 10 ft. width)
- Primitive Road, Administrative Vehicles Only- single lane Type A or Type B
- Trail, Non-Mechanized Non-Motorized Access- Pedestrian and riding livestock
- Decommissioned Route (Not a road or trail)- Restoration
- County or Municipality Maintained Road

Ironwood Forest National Monument:

- Monument Boundary (Proclamation 4320)
- Monument Lands Administered by BLM

NOTE: Only travel routes important to the BLM transportation plan within the travel management planning area are shown on the map.

Monument Land Status: *(NOT SHOWN)*

NOTE: Not all surface management classes may appear on the map. Only management within the study area boundary may be shown.

0 1 2 3 4 5 6 Miles

WARNING:
No warranty is made by the Bureau of Land Management (BLM) for the use of this map for purposes not intended by the BLM, or to the accuracy, reliability, or completeness of the information shown. Spatial information may not meet national Map Accuracy Standards. This information may be updated without notification.

United States Department of the Interior
Bureau of Land Management
Gila District, Tucson Field Office
3201 E. Universal Way
Tucson, AZ 85756

fjm 10/08/14