

US Depart. of the Interior
Bureau of Land Management
Twin Falls District, Idaho

N
W E
S

Rural Telephone Company
Thompson Hill
Fiber Optic ROW

0 0.1 0.2 0.3 0.4 Miles

For internal BLM use only. Review and/or display copy-not for distribution. No warranty is made by the Bureau of Land Management. The accuracy, reliability, or completeness of these data for individual use or aggregate use with other data is not guaranteed.

Boise Meridian,
T. 5 S. R. 10 E. Sec. 25,
T. 5 S. R. 11 E. Sec. 30.

Map Created on: May 3, 2012
Data Displayed in NAD_1983_UTM_Zone_11N Projection
R:\loc\lands\casefiles\ThompsonHill
Author: lclaxton